


MISSOULA

MSO



(JOHNSON BELL FIELD)




MISSOULA

MISSOULA

MSO



(JOHNSON BELL FIELD)





MISSOULA

OPHEIM

S00



OPHEIM



IDENT: S00
CTAF: 122.9

ELEV: 3264'

LOC: 48-52.0 N
106-25.0 W

LIGHTED: LIRL 16/34

FUEL: None

REPAIRS: None

SERVICE: Meals, Lodging ¼ mile

OWNER: City of Opheim & Valley Co.

MANAGER: Marjory Burdette

PHONE: (406)762-3344 or (406)762-3235

REMARKS: Soft when wet. *CAUTION*: Snow removal on request. All rwys have gopher holes.

Beacon out of service indefinitely.



OPHEIM

OPHEIM

S00



OPHEIM



IDENT: S00
CTAF: 122.9

ELEV: 3264'

LOC: 48-52.0 N
106-25.0 W

LIGHTED: LIRL 16/34

FUEL: None

REPAIRS: None

SERVICE: Meals, Lodging ¼ mile

OWNER: City of Opheim & Valley Co.

MANAGER: Marjory Burdette

PHONE: (406)762-3344 or (406)762-3235

REMARKS: Soft when wet. *CAUTION*: Snow removal on request. All rwys have gopher holes.

Beacon out of service indefinitely.



OPHEIM

PHILIPSBURG

U05



(RIDDICK FIELD)



IDENT: U05
CTAF: 122.9

ELEV: 5212'

LOC: 46-19.2 N
113-18.3 W

LIGHTED: Rwy 16/34 R.C. Key 122.9 3,5,7
times. Lighted beacon
FUEL: None
REPAIRS: None
SERVICE: Meals, Lodging 1 ½ miles
OWNER: Granite County

MANAGER: Ty Throope
PHONE: (406)288-3819
REMARKS: Watch for powerline South of
approach end Rwy 34. Right traffic rwy 16.



PHILIPSBURG

PHILIPSBURG

U05



(RIDDICK FIELD)



IDENT: U05
CTAF: 122.9

ELEV: 5212'

LOC: 46-19.2 N
113-18.3 W

LIGHTED: Rwy 16/34 R.C. Key 122.9 3,5,7
times. Lighted beacon
FUEL: None
REPAIRS: None
SERVICE: Meals, Lodging 1 ½ miles
OWNER: Granite County

MANAGER: Ty Throope
PHONE: (406)288-3819
REMARKS: Watch for powerline South of
approach end Rwy 34. Right traffic rwy 16.


PHILIPSBURG

PLAINS

S34



PLAINS




PLAINS

PLAINS

S34



PLAINS





PLAINS

PLENTYWOOD

PWD



(SHER/WOOD)



IDENT: PWD
CTAF: 122.8

ELEV: 2250'

LOC: 48-47.4 N
104-32.0 W

LIGHTED: Rwy 12/30 R.C. Key 122.8 3,5,7 times. Lighted beacon
FUEL: 100LL (24hr credit card pump)
REPAIRS: None
SERVICE: Meals, Lodging 2 miles. Courtesy Car available.
OWNER: City of Plentywood & Sheridan County

MANAGER: Sheridan County
PHONE: (406)765-1660 or (406)286-5452
REMARKS: Phone on field. No snow removal from any turf runway. Rwy 8/26 may be closed for repairs – check NOTAMS. Aerial spraying activity on field. Ultralight and RC activity in vicinity of airport.



PLENTYWOOD

PLENTYWOOD

PWD



(SHER/WOOD)



IDENT: PWD
CTAF: 122.8

ELEV: 2250'

LOC: 48-47.4 N
104-32.0 W

LIGHTED: Rwy 12/30 R.C. Key 122.8 3,5,7 times. Lighted beacon
FUEL: 100LL (24hr credit card pump)
REPAIRS: None
SERVICE: Meals, Lodging 2 miles. Courtesy Car available.
OWNER: City of Plentywood & Sheridan County

MANAGER: Sheridan County
PHONE: (406)765-1660 or (406)286-5452
REMARKS: Phone on field. No snow removal from any turf runway. Rwy 8/26 may be closed for repairs – check NOTAMS. Aerial spraying activity on field. Ultralight and RC activity in vicinity of airport.


PLENTYWOOD

POLSON

8S1



POLSON




POLSON

POLSON

8S1



POLSON




POLSON

POPLAR

42S




POPLAR



Nav.Aids

None



Radio

UNICOM
122.8IDENT: 42S
CTAF: 122.8

ELEV: 2005'

LOC: 48-07.0 N
105-11.3 W

LIGHTED: Rwy 9/27 & VASI rwy 27 R.C. Key 122.8 3 5,7 times. Lighted beacon

FUEL: 100LL

REPAIRS: Minor

SERVICE: Meals, Lodging ½ mile

OWNER: City of Poplar

MANAGER: Dallas O'Connor

PHONE: (406)768-3800

REMARKS: Call 768-3800 or UNICOM for information regarding seaplane fueling on Missouri River adjacent to town.


POPLAR

POPLAR

42S




POPLAR



Nav.Aids

None



Radio

UNICOM
122.8IDENT: 42S
CTAF: 122.8

ELEV: 2005'

LOC: 48-07.0 N
105-11.3 W

LIGHTED: Rwy 9/27 & VASI rwy 27 R.C. Key 122.8 3 5,7 times. Lighted beacon

FUEL: 100LL

REPAIRS: Minor

SERVICE: Meals, Lodging ½ mile

OWNER: City of Poplar

MANAGER: Dallas O'Connor

PHONE: (406)768-3800

REMARKS: Call 768-3800 or UNICOM for information regarding seaplane fueling on Missouri River adjacent to town.


POPLAR

RED LODGE

RED



RED LODGE




RED LODGE

RED LODGE

RED



RED LODGE




RED LODGE

RICHEY

7U8




RICHEY



Nav.Aids

None



Radio

CTAF
122.9IDENT: 7U8
CTAF: 122.9

ELEV: 2493'

LOC: 47-37.6 N
105-04.6 WLIGHTED: LIRL rwy 14/32 R.C. Key 122.9
three times.

FUEL: None

REPAIRS: None

SERVICE: Meals, Lodging 1 mile

OWNER: State of Montana

MANAGER: Montana Aeronautics Division

PHONE: (406)444-2506

REMARKS: Center of runway soft - graded dirt.

No snow removal. Muddy when wet. For

information on airport conditions contact Nils

Sikvland at 773-5835.


RICHEY

RICHEY

7U8




RICHEY



Nav.Aids

None



Radio

CTAF
122.9IDENT: 7U8
CTAF: 122.9

ELEV: 2493'

LOC: 47-37.6 N
105-04.6 WLIGHTED: LIRL rwy 14/32 R.C. Key 122.9
three times.

FUEL: None

REPAIRS: None

SERVICE: Meals, Lodging 1 mile

OWNER: State of Montana

MANAGER: Montana Aeronautics Division

PHONE: (406)444-2506

REMARKS: Center of runway soft - graded dirt.

No snow removal. Muddy when wet. For

information on airport conditions contact Nils

Sikvland at 773-5835.


RICHEY

ROCK CREEK

RCO



(ELIOTT FIELD) ROCK CREEK




ROCK CREEK

ROCK CREEK

RCO



(ELIOTT FIELD) ROCK CREEK




ROCK CREEK

RONAN


7S0



RONAN

**Nav.Aids**

None

**Radio**UNICOM
122.8IDENT: 7S0
CTAF: 122.8

ELEV: 3089'

LOC: 47-34.2 N
114-05.8 W

LIGHTED: MIRL & PAPIs Rwy 6/34 34 R.C.
Key 122.8 3,5,7 times. Lighted beacon
FUEL: 100LL, Jet A (24 hr credit card pump)
REPAIRS: Major
SERVICE: Meals, Lodging 3 miles
OWNER: City of Ronan & Lake County

MANAGER: Craig Elvernd
PHONE: (406)676-2474 (Airport Lounge)
REMARKS: Large seagulls on and in vicinity of airport. Access to pilots lounge - 12151. Phone in lounge.


RONAN

RONAN


7S0



RONAN

**Nav.Aids**

None

**Radio**UNICOM
122.8IDENT: 7S0
CTAF: 122.8

ELEV: 3089'

LOC: 47-34.2 N
114-05.8 W

LIGHTED: MIRL & PAPIs Rwy 6/34 34 R.C.
Key 122.8 3,5,7 times. Lighted beacon
FUEL: 100LL, Jet A (24 hr credit card pump)
REPAIRS: Major
SERVICE: Meals, Lodging 3 miles
OWNER: City of Ronan & Lake County

MANAGER: Craig Elvernd
PHONE: (406)676-2474 (Airport Lounge)
REMARKS: Large seagulls on and in vicinity of airport. Access to pilots lounge - 12151. Phone in lounge.



RONAN

ROUNDUP

RPX



ROUNDUP

| | | | |
|--|--------------------|--|--|
| AIRPORT LOCATION  | | Nav.Aids RPX NDB 362 | |
| AIRPORT LAYOUT  | | Radio UNICOM 122.8 | |
| IDENT: RPX CTAF: 122.8 | ELEV: 3485' | LOC: 46-28.4 N 108-33.5 W | |
| LIGHTED: Rwy 6/24 & PAPI rwy 24 R.C. Key 122.8 3,5,7 times. Lighted beacon. FUEL: 100LL, Jet A Credit Card self service REPAIRS: Minor SERVICE: Courtesy car. Meals, Lodging 2 ½ miles. OWNER: City of Roundup & Musselshell County | | | MANAGER: Jake Barthule PHONE: (406)323-1426 cell (406)320-1252 REMARKS: Phone on field. Right traffic rwy 24 from 22:00L to 07:00L. Radio controlled aircraft on and in vicinity of airport. **Super Awos** is activated on 122.8 with 3 clicks of MIC. |



ROUNDUP

ROUNDUP

RPX



ROUNDUP

| | | | |
|--|--------------------|--|--|
| AIRPORT LOCATION | | Nav.Aids RPX NDB 362 | |
|  | | | |
| AIRPORT LAYOUT | | Radio UNICOM 122.8 | |
|  | | | |
| IDENT: RPX CTAF: 122.8 | ELEV: 3485' | LOC: 46-28.4 N 108-33.5 W | |
| LIGHTED: Rwy 6/24 & PAPI rwy 24 R.C. Key 122.8 3,5,7 times. Lighted beacon. FUEL: 100LL, Jet Credit Card self service REPAIRS: Minor SERVICE: Courtesy car. Meals, Lodging 2 ½ miles. OWNER: City of Roundup & Musselshell County | | | MANAGER: Jake Barthule PHONE: (406)323-1426 cell (406)320-1252 REMARKS: Phone on field. Right traffic rwy 24 from 22:00L to 07:00L. Radio controlled aircraft on and in vicinity of airport. **Super Awos** is activated on 122.8 with 3 clicks of MIC. |



ROUNDUP

RYEGATE

8U0



RYEGATE



| | | |
|---------------------------|-------------|------------------------------|
| IDENT: 8U0 CTAF: 122.9 | ELEV: 3700' | LOC: 46-17.0 N 109-15.0 W |
|---------------------------|-------------|------------------------------|

| | |
|--|---|
| LIGHTED: Beacon FUEL: None REPAIRS: None SERVICE: Meals, Lodging 1 mile OWNER: State of Montana | MANAGER: Montana Aeronautics Division PHONE: (406)444-2506 REMARKS: Pilot registration desk. May be soft when wet. No snow removal. *NOTE*: for airport information contact Richard Shifley at 568-2529. |
|--|---|



RYEGATE

RYEGATE

8U0



RYEGATE



| | | |
|---------------------------|-------------|------------------------------|
| IDENT: 8U0 CTAF: 122.9 | ELEV: 3700' | LOC: 46-17.0 N 109-15.0 W |
|---------------------------|-------------|------------------------------|

| | |
|--|---|
| LIGHTED: Beacon FUEL: None REPAIRS: None SERVICE: Meals, Lodging 1 mile OWNER: State of Montana | MANAGER: Montana Aeronautics Division PHONE: (406)444-2506 REMARKS: Pilot registration desk. May be soft when wet. No snow removal. *NOTE*: for airport information contact Richard Shifley at 568-2529. |
|--|---|



RYEGATE

SAND SPRINGS

8U1



SAND SPRINGS



IDENT: 8U1
CTAF: 122.9

ELEV: 3180'

LOC: 47-06.1 N
107-30.2 W

LIGHTED: None

FUEL: None

REPAIRS: None

SERVICE: Courtesy Car, Meals ¼ mile.

OWNER: Dutton Enterprises

MANAGER: Leo Dutton

PHONE: (406)449-8182

REMARKS: Call 557-6144 for condition of field or fuel. UNICOM located at Sand Springs Store next to runway is not usually monitored. TPA 3900 (720' AGL). Mogas available at adjacent store.



SAND SPRINGS

SAND SPRINGS

8U1



SAND SPRINGS



IDENT: 8U1
CTAF: 122.9

ELEV: 3180'

LOC: 47-06.1 N
107-30.2 W

LIGHTED: None

FUEL: None

REPAIRS: None

SERVICE: Courtesy Car, Meals ¼ mile.

OWNER: Dutton Enterprises

MANAGER: Leo Dutton

PHONE: (406)449-8182

REMARKS: Call 557-6144 for condition of field or fuel. UNICOM located at Sand Springs Store next to runway is not usually monitored. TPA 3900 (720' AGL). Mogas available at adjacent store.



SAND SPRINGS

SCHAFER MEADOWS

8U2



(U.S.F.S. WILDERNESS)
SCHAFER



| | | |
|---|--------------------|--|
| IDENT: 8U2 CTAF: 122.9 | ELEV: 4855' | LOC: 48-05.2 N 113-15.1 W |
|---|--------------------|--|

| | |
|---|--|
| <p>LIGHTED: None FUEL: None REPAIRS: None SERVICE: None OWNER: U.S. Forest Service *NOTE*: DUE TO DESIGNATED WILDERNESS, SHORT DURATION STOPS OR FLIGHT TRAINING IS DISCOURAGED.</p> | <p>MANAGER: Deb Mucklow, District Ranger, Spotted Bear Ranger Dist. PHONE: (406)758-5376 Summer, (406)387-3800 Winter REMARKS: *CAUTION*: Horses, deer, moose and bear frequently on runway. Land and takeoff to the west. Gopher holes in runway. Recommended for experienced pilots only. Good camping facilities. Please leave camping area clean. No generators allowed for camping. Appx. 1/2 of runway length is marked with white cones (2100').</p> |
|---|--|



SCHAFER MEADOWS

SCHAFER MEADOWS

8U2



(U.S.F.S. WILDERNESS)
SCHAFER



| | | |
|---|--------------------|--|
| IDENT: 8U2 CTAF: 122.9 | ELEV: 4855' | LOC: 48-05.2 N 113-15.1 W |
|---|--------------------|--|

| | |
|---|--|
| <p>LIGHTED: None FUEL: None REPAIRS: None SERVICE: None OWNER: U.S. Forest Service *NOTE*: DUE TO DESIGNATED WILDERNESS, SHORT DURATION STOPS OR FLIGHT TRAINING IS DISCOURAGED.</p> | <p>MANAGER: Deb Mucklow, District Ranger, Spotted Bear Ranger Dist. PHONE: (406)758-5376 Summer, (406)387-3800 Winter REMARKS: *CAUTION*: Horses, deer, moose and bear frequently on runway. Land and takeoff to the west. Gopher holes in runway. Recommended for experienced pilots only. Good camping facilities. Please leave camping area clean. No generators allowed for camping. Appx. 1/2 of runway length is marked with white cones (2100').</p> |
|---|--|


SCHAFER MEADOWS

SCOBEEY


9S2



SCOBEEY



Nav.Aids

SCO NDB
283

Radio

UNICOM
122.8IDENT: 9S2
CTAF: 122.8

ELEV: 2433'

LOC: 48-48.4 N
105-26.5 WLIGHTED: MIRL & PAPI rwy 12/30 R.C. Key
122.8 5,7 times after 2300L. Lighted beacon

FUEL: 100LL, JetA

REPAIRS: Major

SERVICE: Meals, Lodging 1 mile

OWNER: City of Scobey & Daniels County

MANAGER: Charles Trower

PHONE: (406)487-2725

REMARKS: Phone on field. For fuel after hours
call 487-5544**Super Awos** is activated on 122.8 with 3 clicks
of MIC. Scobey border station is East Poplar.


SCOBEEY

SCOBEEY


9S2



SCOBEEY



Nav.Aids

SCO NDB
283

Radio

UNICOM
122.8IDENT: 9S2
CTAF: 122.8

ELEV: 2433'

LOC: 48-48.4 N
105-26.5 WLIGHTED: MIRL & PAPI rwy 12/30 R.C. Key
122.8 5,7 times after 2300L. Lighted beacon

FUEL: 100LL, JetA

REPAIRS: Major

SERVICE: Meals, Lodging 1 mile

OWNER: City of Scobey & Daniels County

MANAGER: Charles Trower


PHONE: (406)487-2725

REMARKS: Phone on field. For fuel after hours
call 487-5544**Super Awos** is activated on 122.8 with 3 clicks
of MIC. Scobey border station is East Poplar.

SCOBEEY

SEELEY LAKE (1) **23S**


SEELEY LAKE (1)




SEELEY LAKE (1)

SEELEY LAKE (1) **23S**


SEELEY LAKE (1)



SEELEY LAKE (1)



SEELEY LAKE (2)




SEELEY LAKE (2)

SHELBY

SBX



SHELBY




SHELBY

SHELBY

SBX



SHELBY





SHELBY

SPOTTED BEAR

8U4



SPOTTED BEAR



IDENT: 8U4
CTAF: 122.9

ELEV: 3670'

LOC: 47-57.5 N
113-33.6 W

LIGHTED: None
FUEL: None
REPAIRS: None
SERVICE: None
OWNER: U.S. Forest Service

MANAGER: Deb Mucklow, District Ranger, Spotted Bear Ranger Dist.
PHONE: (406)758-5376 Summer, (406)387-3800 Winter
REMARKS: Phone available at Spotted Bear Station 3 miles from runway (USFS Private Line) Apr.-Nov. Overruns each rwy end very rough. Last 450' north end of rwy rough. Recommended for experienced pilots only.



SPOTTED BEAR

SPOTTED BEAR

8U4



SPOTTED BEAR



IDENT: 8U4
CTAF: 122.9

ELEV: 3670'

LOC: 47-57.5 N
113-33.6 W

LIGHTED: None
FUEL: None
REPAIRS: None
SERVICE: None
OWNER: U.S. Forest Service

MANAGER: Deb Mucklow, District Ranger, Spotted Bear Ranger Dist.
PHONE: (406)758-5376 Summer, (406)387-3800 Winter
REMARKS: Phone available at Spotted Bear Station 3 miles from runway (USFS Private Line) Apr.-Nov. Overruns each rwy end very rough. Last 450' north end of rwy rough. Recommended for experienced pilots only.



SPOTTED BEAR

ST. IGNATIUS

52S



ST. IGNATIUS



IDENT: 52S
CTAF: 122.9

ELEV: 3006'

LOC: 47-19.5 N
114-04.8 W

LIGHTED: MIRL rwy 8/26 R.C. Key 122.9 5 times. Lighted beacon

FUEL: 100LL, credit card, self service

REPAIRS: Yes

SERVICE: Meals, Lodging 1 ½ miles, courtesy car

OWNER: City of St. Ignatus & Lake County

MANAGER: Gail Anderson

PHONE: (406)745-4008

REMARKS: Phone on field (745-4008). Pilot registration desk. 2277' available for night ops. Pilot lounge. Note runway slope. Caution seagulls on field.



ST. IGNATIUS

ST. IGNATIUS

52S



ST. IGNATIUS



IDENT: 52S
CTAF: 122.9

ELEV: 3006'

LOC: 47-19.5 N
114-04.8 W

LIGHTED: MIRL rwy 8/26 R.C. Key 122.9 5 times. Lighted beacon

FUEL: 100LL, credit card, self service

REPAIRS: Yes

SERVICE: Meals, Lodging 1 ½ miles, courtesy car

OWNER: City of St. Ignatus & Lake County

MANAGER: Gail Anderson

PHONE: (406)745-4008

REMARKS: Phone on field (745-4008). Pilot registration desk. 2277' available for night ops. Pilot lounge. Note runway slope. Caution seagulls on field.



ST. IGNATIUS

STANFORD

S64



STANFORD



IDENT: S64
CTAF: 122.8

ELEV: 4318'

LOC: 47-08.8 N
110-13.8 W

LIGHTED: Rwy 11/29 & PAPI rwy 29 R.C.
Key 122.8 3,5,7 times. Lighted beacon
FUEL: 100LL
REPAIRS: None
SERVICE: Meals, Lodging adjacent
OWNER: Judith Basin County

MANAGER: Mike Biggerstaff
PHONE: (406)566-2236
REMARKS: 200' grain elevator on downwind for rwy 11. Power line on approach to rwy 25. Caution for model aircraft activity on and around airport. Numerous ag spraying ops. 110' tower 3.1 miles west of airport, top of tower is 4820' MSL.



STANFORD

STANFORD

S64



STANFORD



IDENT: S64
CTAF: 122.8

ELEV: 4318'

LOC: 47-08.8 N
110-13.8 W

LIGHTED: Rwy 11/29 & PAPI rwy 29 R.C.
Key 122.8 3,5,7 times. Lighted beacon
FUEL: 100LL
REPAIRS: None
SERVICE: Meals, Lodging adjacent
OWNER: Judith Basin County

MANAGER: Mike Biggerstaff
PHONE: (406)566-2236
REMARKS: 200' grain elevator on downwind for rwy 11. Power line on approach to rwy 25. Caution for model aircraft activity on and around airport. Numerous ag spraying ops. 110' tower 3.1 miles west of airport, top of tower is 4820' MSL.

STANFORD

STEVENSVILLE

32S



STEVENSVILLE

| | | |
|--|--------------------|---|
| AIRPORT LOCATION | | Nav.Aids None |
| AIRPORT LAYOUT | | Radio UNICOM 122.8 |
| IDENT: 32S CTAF: 122.8 | ELEV: 3610' | LOC: 46-31.5 N 114-03.1 W |
| LIGHTED: Rwy 12/30 & PAPI rwy 12. Key 122.8 3,5,7 times. Lighted beacon FUEL: 100LL (self serve) REPAIRS: Major SERVICE: Meals, Lodging 3 miles OWNER: Town of Stevensville | | MANAGER: Don Misevic PHONE: (406)777-2006 or (406)777-5271 REMARKS: Phone on field. Snow removal intermittent. Land rwy 12 & T/O rwy 30 wind permitting. |

STEVENSVILLE

STEVENSVILLE

32S



STEVENSVILLE

| | | |
|--|--------------------|---|
| AIRPORT LOCATION | | Nav.Aids None |
| AIRPORT LAYOUT | | Radio UNICOM 122.8 |
| IDENT: 32S CTAF: 122.8 | ELEV: 3610' | LOC: 46-31.5 N 114-03.1 W |
| LIGHTED: Rwy 12/30 & PAPI rwy 12. Key 122.8 3,5,7 times. Lighted beacon FUEL: 100LL (self serve) REPAIRS: Major SERVICE: Meals, Lodging 3 miles OWNER: Town of Stevensville | | MANAGER: Don Misevic PHONE: (406)777-2006 or (406)777-5271 REMARKS: Phone on field. Snow removal intermittent. Land rwy 12 & T/O rwy 30 wind permitting. |


STEVENSVILLE

SUNBURST

8U5




SUNBURST



Nav.Aids

None



Radio

CTAF
122.9IDENT: 8U5
CTAF: 122.9

ELEV: 3401'

LOC: 48-53.2 N
111-55.3 W

LIGHTED: None

FUEL: None

REPAIRS: None

SERVICE: Meals ½ mile.

OWNER: Toole County

MANAGER: Hank Coolidge

PHONE: (406)937-7400 or (406)937-3985 or
(406)460-7400 MobileREMARKS: Right Traffic rwy 23. Pilot
Registration desk. *CAUTION*: Rwy 05/23 &
18/36 may have large gopher holes and be
rough.


SUNBURST

SUNBURST

8U5




SUNBURST



Nav.Aids

None



Radio

CTAF
122.9IDENT: 8U5
CTAF: 122.9

ELEV: 3401'

LOC: 48-53.2 N
111-55.3 W

LIGHTED: None

FUEL: None

REPAIRS: None

SERVICE: Meals ½ mile.

OWNER: Toole County

MANAGER: Hank Coolidge

PHONE: (406)937-7400 or (406)937-3985 or
(406)460-7400 MobileREMARKS: Right Traffic rwy 23. Pilot
Registration desk. *CAUTION*: Rwy 05/23 &
18/36 may have large gopher holes and be
rough.



SUNBURST

SUPERIOR

9S4



(MINERAL COUNTY)



| | | |
|---|--------------------|--|
| IDENT: 9S4 CTAF: 122.9 | ELEV: 2780' | LOC: 47-10.1 N 114-51.2 W |
|---|--------------------|--|

| | |
|---|---|
| LIGHTED: None (see remarks) FUEL: None REPAIRS: None SERVICE: Meals, Lodging 2.8 miles OWNER: Mineral County | MANAGER: Gerald Geske PHONE: (406)822-4917 REMARKS: *CAUTION*: Mountainous terrain surrounding airport. Airport not intended for night operations. Rwy lights intended for EMERGENCY use only. |
|---|---|



SUPERIOR

SUPERIOR

9S4



(MINERAL COUNTY)



| | | |
|---|--------------------|--|
| IDENT: 9S4 CTAF: 122.9 | ELEV: 2780' | LOC: 47-10.1 N 114-51.2 W |
|---|--------------------|--|

| | |
|---|---|
| LIGHTED: None (see remarks) FUEL: None REPAIRS: None SERVICE: Meals, Lodging 2.8 miles OWNER: Mineral County | MANAGER: Gerald Geske PHONE: (406)822-4917 REMARKS: *CAUTION*: Mountainous terrain surrounding airport. Airport not intended for night operations. Rwy lights intended for EMERGENCY use only. |
|---|---|


SUPERIOR

SWEETGRASS

7S8



(ROSS INTERNATIONAL)




SWEETGRASS

SWEETGRASS

7S8



(ROSS INTERNATIONAL)




SWEETGRASS

TERRY

8U6




TERRY



Nav.Aids

None



Radio

CTAF
122.9IDENT: 8U6
CTAF: 122.9

ELEV: 2281'

LOC: 46-46.8 N
105-18.3 WLIGHTED: Rwy 7/25 and beacon R.C. Key
122.9 3,5,7 times. (see remarks)

FUEL: None

REPAIRS: None

SERVICE: Meals, Lodging 2 miles

OWNER: Prairie County Airport Authority

MANAGER: Willis Bartholomay

PHONE: (406)637-5459

REMARKS: Pay phone on field. MIRL may be out
of service, check with manager. Snow removal
intermittant.


TERRY

TERRY

8U6




TERRY



Nav.Aids

None



Radio

CTAF
122.9IDENT: 8U6
CTAF: 122.9

ELEV: 2281'

LOC: 46-46.8 N
105-18.3 WLIGHTED: Rwy 7/25 and beacon R.C. Key
122.9 3,5,7 times. (see remarks)

FUEL: None

REPAIRS: None

SERVICE: Meals, Lodging 2 miles

OWNER: Prairie County Airport Authority

MANAGER: Willis Bartholomay

PHONE: (406)637-5459

REMARKS: Pay phone on field. MIRL may be out
of service, check with manager. Snow removal
intermittant.

TERRY

THOMPSON
FALLS

THM



THOMPSON FALLS

| | | |
|--|--------------------|--|
| AIRPORT LOCATION | | Nav.Aids None |
| AIRPORT LAYOUT | | Radio CTAF 122.9 |
| IDENT: THM CTAF: 122.9 | ELEV: 2466' | LOC: 47-34.2 N 115-16.5 W |
| LIGHTED: Rwy 7/25 & VASI rwy 25 & PAPI rwy 7. R.C. Key 122.9 3,5,7 times. Lighted beacon FUEL: 100LL (w/ credit card) REPAIRS: None SERVICE: Motel (406)827-3536. Meals, Lodging 2 miles. OWNER: Sanders County | | |

THOMPSON FALLS

THOMPSON
FALLS

THM



THOMPSON FALLS

| | | |
|--|--------------------|--|
| AIRPORT LOCATION | | Nav.Aids None |
| AIRPORT LAYOUT | | Radio CTAF 122.9 |
| IDENT: THM CTAF: 122.9 | ELEV: 2466' | LOC: 47-34.2 N 115-16.5 W |
| LIGHTED: Rwy 7/25 & VASI rwy 25 & PAPI rwy 7. R.C. Key 122.9 3,5,7 times. Lighted beacon FUEL: 100LL (w/ credit card) REPAIRS: None SERVICE: Motel (406)827-3536. Meals, Lodging 2 miles. OWNER: Sanders County | | |


THOMPSON FALLS

THREE FORKS

9S5



(POGREBA FIELD)




THREE FORKS

THREE FORKS

9S5



(POGREBA FIELD)




THREE FORKS


TIBER DAM

B70

(OLD IDENT MT70) TIBER DAM

**Nav.Aids**

None

**Radio**

CTAF
122.9
GTF FSS
RCO
122.2 at
pattern
altitude and
above.

IDENT: B70
CTAF: 122.9

ELEV: 3023'

LOC: 48-18.8 N
111-06.5 W

LIGHTED: None

FUEL: None

REPAIRS: None

SERVICE: None

OWNER: State of Montana

MANAGER: Montana Aeronautics Division

PHONE: (406)444-2506


REMARKS: No snow removal. Rwy may be rough.

TIBER DAM


TIBER DAM

B70

(OLD IDENT MT70) TIBER DAM

**Nav.Aids**

None

**Radio**

CTAF
122.9
GTF FSS
RCO
122.2 at
pattern
altitude and
above.

IDENT: B70
CTAF: 122.9

ELEV: 3023'

LOC: 48-18.8 N
111-06.5 W

LIGHTED: None

FUEL: None

REPAIRS: None

SERVICE: None

OWNER: State of Montana

MANAGER: Montana Aeronautics Division

PHONE: (406)444-2506

REMARKS: No snow removal. Rwy may be rough.

TIBER DAM

TOWNSEND



8U8



TOWNSEND

Nav.Aids

None



IDENT: 8U8
CTAF: 122.8

ELEV: 3885'

LOC: 46-19.9 N
111-28.9 W

LIGHTED: Rwy 16/34 R.C. Key 122.8 3,5,7 times. Lighted beacon

FUEL: 100LL Self-Serve

REPAIRS: Minor

SERVICE: Meals ¼ mile south. Lodging 2 miles

OWNER: City of Townsend and Broadwater County

MANAGER: Neil Salmi
PHONE: (406)266-5400

REMARKS: Taxiway marked with reflectors. Airport unattended. Pilot lounge on field. Phone on field. Courtesy van available.



TOWNSEND

TOWNSEND

8U8



TOWNSEND



IDENT: 8U8
CTAF: 122.8

ELEV: 3885'

LOC: 46-19.9 N
111-28.9 W

LIGHTED: Rwy 16/34 R.C. Key 122.8 3,5,7 times. Lighted beacon

FUEL: 100LL Self-Serve

REPAIRS: Minor

SERVICE: Meals ¼ mile south. Lodging 2 miles

OWNER: City of Townsend and Broadwater County

MANAGER: Neil Salmi
PHONE: (406)266-5400

REMARKS: Taxiway marked with reflectors. Airport unattended. Pilot lounge on field. Phone on field. Courtesy van available.


TOWNSEND

TROY

57S



(U.S.F.S.) TROY




TROY

TROY

57S



(U.S.F.S.) TROY




TROY

TURNER

9U0




TURNER



Nav.Aids

None



Radio

CTAF
122.9IDENT: 9U0
CTAF: 122.9

ELEV: 3049'

LOC: 48-51.3 N
108-24.5 W

LIGHTED: Rwy 7/25 & VASI rwy 25 R.C. Key 122.9 3,5,7 times after 22:00L. Lighted beacon

FUEL: None

REPAIRS: Minor

SERVICE: Meals, Lodging adjacent

OWNER: Blaine County

MANAGER: Jon Harmon

PHONE: (406)379-2501 Home or (406)379-2584 Work

REMARKS: Runway 28 rough with gopher holes. For service after hours call 379-2214. Beacon may be out of service.


TURNER

TURNER

9U0




TURNER



Nav.Aids

None



Radio

CTAF
122.9IDENT: 9U0
CTAF: 122.9

ELEV: 3049'

LOC: 48-51.3 N
108-24.5 W

LIGHTED: Rwy 7/25 & VASI rwy 25 R.C. Key 122.9 3,5,7 times after 22:00L. Lighted beacon

FUEL: None

REPAIRS: Minor

SERVICE: Meals, Lodging adjacent

OWNER: Blaine County

MANAGER: Jon Harmon

PHONE: (406)379-2501 Home or (406)379-2584 Work

REMARKS: Runway 28 rough with gopher holes. For service after hours call 379-2214. Beacon may be out of service.


TURNER

TWIN BRIDGES

7S1



TWIN BRIDGES




TWIN BRIDGES

TWIN BRIDGES

7S1



TWIN BRIDGES




TWIN BRIDGES

VALIER

7S7



VALIER




VALIER

VALIER

7S7



VALIER



VALIER

WEST POPLAR

JF5



(CANADIAN)

| | | |
|--|--------------------|---|
| AIRPORT LOCATION | | Nav.Aids None |
| AIRPORT LAYOUT | | Radio CTAF 123.2 |
| IDENT: JF5 CTAF: 123.2 | ELEV: 2885' | LOC: 49-00.0 N 106-23.0 W |
| LIGHTED: None FUEL: None REPAIRS: None SERVICE: None OWNER: Canadian Government | | MANAGER: Canadian Customs (see remarks) PHONE: (306) 476-2320 U.S. Customs (406)724-3212 Can. Customs (306)476-2320 or 888-226-7277 (call ahead for hours) REMARKS: Canadian Customs only, no U.S. Customs for aircraft. *CAUTION*: Airport lies entirely within Canada. Rwy may be rough or soft when wet. No snow removal. If unable to contact Customs, contact MT Pilots Assn, Valley Hangar at 228-4023 or contact T. Hanson at 762-3265. Possible unknown adverse conditions. |

WEST POPLAR

WEST POPLAR

JF5



(CANADIAN)

| | | |
|--|--------------------|---|
| AIRPORT LOCATION | | Nav.Aids None |
| AIRPORT LAYOUT | | Radio CTAF 123.2 |
| IDENT: JF5 CTAF: 123.2 | ELEV: 2885' | LOC: 49-00.0 N 106-23.0 W |
| LIGHTED: None FUEL: None REPAIRS: None SERVICE: None OWNER: Canadian Government | | MANAGER: Canadian Customs (see remarks) PHONE: (306) 476-2320 U.S. Customs (406)724-3212 Can. Customs (306)476-2320 or 888-226-7277 (call ahead for hours) REMARKS: Canadian Customs only, no U.S. Customs for aircraft. *CAUTION*: Airport lies entirely within Canada. Rwy may be rough or soft when wet. No snow removal. If unable to contact Customs, contact MT Pilots Assn, Valley Hangar at 228-4023 or contact T. Hanson at 762-3265. Possible unknown adverse conditions. |


WEST POPLAR

WEST YELLOWSTONE

WYS




(YELLOWSTONE)



Nav.Aids

ESY NDB
338
ILS rwy 01
110.7
LOM
415



Radio

UNICOM
123.0
GTF FSS
RCO
119.4
SLC APP
CON
132.4

IDENT: WYS
CTAF: 123.0
ELEV: 6644'
LOC: 44-41.3 N
111-07.1 W

LIGHTED: HIRL rwy 1/19 & MALSR & PAPI rwy 01 & VASI & REIL rwy 19 R.C. Key 123.0 3,5,7 times. Lighted beacon
FUEL: 100, Jet A1+
REPAIRS: None
SERVICE: Rental cars, taxis. Meals on field, lodging 2 miles.
OWNER: State of Montana
MANAGER: Montana Aeronautics Division
PHONE: (406)646-7631, (406)444-2506 Winter
REMARKS: Airport open June 1 to Sept. 30. Check NOTAMS. No snow removal. HIRL, MALSR, REIL, PAPI & VASI out of service Oct 1 - May 31. Landing fee for aircraft over 11,000lbs. Free pilots campground on airport. Free bicycles to use at campground.


WEST YELLOWSTONE

WEST YELLOWSTONE

WYS




(YELLOWSTONE)



Nav.Aids

ESY NDB
338
ILS rwy 01
110.7
LOM
415



Radio

UNICOM
123.0
GTF FSS
RCO
119.4
SLC APP
CON
132.4

IDENT: WYS
CTAF: 123.0
ELEV: 6644'
LOC: 44-41.3 N
111-07.1 W

LIGHTED: HIRL rwy 1/19 & MALSR & PAPI rwy 01 & VASI & REIL rwy 19 R.C. Key 123.0 3,5,7 times. Lighted beacon
FUEL: 100, Jet A1+
REPAIRS: None
SERVICE: Rental cars, taxis. Meals on field, lodging 2 miles.
OWNER: State of Montana
MANAGER: Montana Aeronautics Division
PHONE: (406)646-7631, (406)444-2506 Winter
REMARKS: Airport open June 1 to Sept. 30. Check NOTAMS. No snow removal. HIRL, MALSR, REIL, PAPI & VASI out of service Oct 1 - May 31. Landing fee for aircraft over 11,000lbs. Free pilots campground on airport. Free bicycles to use at campground.


WEST YELLOWSTONE

WHITE SULPHUR SPRINGS

7S6



WHITE SULPHUR SPRINGS




WHITE SULPHUR SPRINGS

WHITE SULPHUR SPRINGS

7S6



WHITE SULPHUR SPRINGS





WHITE SULPHUR SPRINGS

WHITEFISH

58S



WHITEFISH

**Nav.Aids**FCA VOR
113.2**Radio**CTAF
122.9IDENT: 58S
CTAF: 122.9

ELEV: 3066'

LOC: 48-24.5 N
114-18.0 W

LIGHTED: None
FUEL: None
REPAIRS: None
SERVICE: Meals, Lodging 3 miles
OWNER: Flathead Municipal Airport Authority

MANAGER: Cindi Martin
PHONE: (406)257-5994
REMARKS: *CAUTION*: Soft when wet. Not maintained in winter. Numerous gopher holes. Check NOTAMs to ensure airport is open during wet season. Airport closed winter months. Free bicycles for airport use in shed. Use emergency frequency to open cipher lock.



WHITEFISH

WHITEFISH

58S



WHITEFISH

**Nav.Aids**FCA VOR
113.2**Radio**CTAF
122.9IDENT: 58S
CTAF: 122.9

ELEV: 3066'

LOC: 48-24.5 N
114-18.0 W

LIGHTED: None
FUEL: None
REPAIRS: None
SERVICE: Meals, Lodging 3 miles
OWNER: Flathead Municipal Airport Authority

MANAGER: Cindi Martin
PHONE: (406)257-5994
REMARKS: *CAUTION*: Soft when wet. Not maintained in winter. Numerous gopher holes. Check NOTAMs to ensure airport is open during wet season. Airport closed winter months. Free bicycles for airport use in shed. Use emergency frequency to open cipher lock.


WHITEFISH

WILSALL

9U1



WILSALL




WILSALL

WILSALL

9U1



WILSALL



WILSALL

WINIFRED

9S7



WINIFRED

| | | |
|--|--------------------|---|
| AIRPORT LOCATION | | Nav.Aids None |
| AIRPORT LOCATION CAUTION MAY BE ROUGH | | Radio CTAF 122.9 |
| IDENT: 9S7 CTAF: 122.9 | ELEV: 3311' | LOC: 47-33.1 N 109-22.7 W |
| LIGHTED: None FUEL: 100/110 by prior arrangement REPAIRS: None SERVICE: Meals, Lodging ½ mile OWNER: City of Winifred & Fergus County | | MANAGER: Steve Ehlert PHONE: (406)462-5357 REMARKS: Hills in west approach zone. Recommend landing rwy 26, takeoff rwy 8. Rwy not mowed and rough. In case of emergency contact the Winnifred cafe at 462-5426. If unable to contact airport manager, contact Tom Econom at 462-5360. |

WINIFRED

WINIFRED

9S7



WINIFRED

| | | |
|--|--------------------|---|
| AIRPORT LOCATION | | Nav.Aids None |
| AIRPORT LOCATION CAUTION MAY BE ROUGH | | Radio CTAF 122.9 |
| IDENT: 9S7 CTAF: 122.9 | ELEV: 3311' | LOC: 47-33.1 N 109-22.7 W |
| LIGHTED: None FUEL: 100/110 by prior arrangement REPAIRS: None SERVICE: Meals, Lodging ½ mile OWNER: City of Winifred & Fergus County | | MANAGER: Steve Ehlert PHONE: (406)462-5357 REMARKS: Hills in west approach zone. Recommend landing rwy 26, takeoff rwy 8. Rwy not mowed and rough. In case of emergency contact the Winnifred cafe at 462-5426. If unable to contact airport manager, contact Tom Econom at 462-5360. |

WINIFRED

WINNETT

(PETROLEUM COUNTY)

| | | |
|---|--------------------|--|
| AIRPORT LOCATION | | Nav.Aids None |
| AIRPORT LAYOUT | | Radio CTAF 122.9 |
| IDENT: CTAF: 122.9 | ELEV: 2960' | LOC: 46-58.6 N 108-21.9 W |
| LIGHTED: None FUEL: None REPAIRS: None SERVICE: Meals, Lodging 2 miles OWNER: Petroleum County | | MANAGER: Ron Solf PHONE: (406)429-6429 REMARKS: *Caution* Unmarked powerline east of airport. For conditions, call Sheriff's office at 429-6551, or manager after business hours. |

WINNETT

WINNETT

(PETROLEUM COUNTY)

| | | |
|---|--------------------|--|
| AIRPORT LOCATION | | Nav.Aids None |
| AIRPORT LAYOUT | | Radio CTAF 122.9 |
| IDENT: CTAF: 122.9 | ELEV: 2960' | LOC: 46-58.6 N 108-21.9 W |
| LIGHTED: None FUEL: None REPAIRS: None SERVICE: Meals, Lodging 2 miles OWNER: Petroleum County | | MANAGER: Ron Solf PHONE: (406)429-6429 REMARKS: *Caution* Unmarked powerline east of airport. For conditions, call Sheriff's office at 429-6551, or manager after business hours. |

WINNETT

WISDOM

7S4



WISDOM

| | | |
|--|--------------------|--|
| AIRPORT LOCATION | | Nav.Aids None |
| AIRPORT LAYOUT CAUTION FIELD ROUGH | | Radio MULTICOM 122.9 |
| IDENT: 7S4 CTAF: 122.9 | ELEV: 6133' | LOC: 45-35.5 N 113-27.6 W |
| LIGHTED: None FUEL: None REPAIRS: None SERVICE: Meals, Lodging 2 miles OWNER: Beverhead County MANAGER: Dennis and Jean DeVivo PHONE: (406)683-5242 REMARKS: *CAUTION*: Field may be rough. No snow removal. Closed winter months. First 1000' of each rwy end marked with cones. Rwy 19 has displaced threshold. For local conditions call Larry Tucker at 683-2383. For after hours information, contact Dennis DeVivo at (406) 683-5669 or (406)660-0734 | | |

WISDOM

WISDOM

7S4



WISDOM

| | | |
|---|--------------------|--|
| AIRPORT LOCATION | | Nav.Aids None |
| AIRPORT LAYOUT CAUTION FIELD ROUGH | | Radio MULTICOM 122.9 |
| IDENT: 7S4 CTAF: 122.9 | ELEV: 6133' | LOC: 45-35.5 N 113-27.6 W |
| LIGHTED: None FUEL: None REPAIRS: None SERVICE: Meals, Lodging 2 miles OWNER: Beverhead County MANAGER: Dennis and Jean DeVivo PHONE: (406)683-5242 REMARKS: *CAUTION*: Field may be rough. No snow removal. Closed winter months. First 1000' of each rwy end marked with cones. Rwy 19 has displaced threshold. For local conditions call Larry Tucker at 683-2383. For after hours information, contact Dennis DeVivo at (406)683-5669 or (406)660-0734 | | |


WISDOM

WISE RIVER

02T



WISE RIVER




WISE RIVER

WISE RIVER

02T



WISE RIVER




WISE RIVER

WOLF POINT

OLF



(LYMAN CLAYTON)




WOLF POINT

WOLF POINT

OLF



(LYMAN CLAYTON)



WOLF POINT